


The most important safety rules at the Würzburg site



Please read the safety rules

before entering our location and observe them during your stay!
As a general rule,

no work without a risk assessment / permit!



Arbeiten immer mit dem Arbeits-erlaubnisschein autorisieren.



In the event of a medical emergency, accident, fire, pollution, traffic accident or damage caused by other hazards, you must call the factory emergency number immediately. **Please save the emergency number on your mobile phone before your assignment.**



112 Emergency call (fire, accident, ambulance)

0931/9084-222 (emergency call)

Other important phone numbers:

0931/9084-251

0931/9084-212 **Occupational health**

0931/9084-218 **Plant Security Gate 1**

0931/9084-295 **Company Fire Brigade**

0931/9084-385 **Responsible Care**

Mobile 0173/3798956

Important information when making an emergency call:



- Where** Did it happen?
- What** Happened?
- How many** Injured?
- Which one** Injury?
- Wait** Do you have any questions?



- Bring to safety
- Warn people
- Taking helpless people with you



In the **event of an alarm**, the assembly point assigned to the Würzburg location must be visited immediately and the completeness must be determined.

Rescuing people takes precedence over firefighting!



CO2 extinguishing areas are marked by yellow signs at the entrances. These areas are protected by an automatic fire-fighting device.

If the horn sounds, leave the building immediately and go to the collection point. There is an acute danger to life!

After the warning time (30 seconds) has elapsed, the doors and windows close automatically. The doors can still be opened manually at any time. Inhalation of elevated carbon dioxide concentrations leads to death by suffocation after a very short time. Work in which it is not possible to leave the rooms within the warning time, e.g. driving on containers, working on scaffolding, lifting equipment, etc., may only be started once the automatic CO2 extinguishing has been taken out of service by the company fire brigade. The documentation is provided in the permit form. Emergency exit doors, escape routes, stairs, other entrances/exits must not be blocked or their automatic closure may not be overridden.



The most important safety rules at the Würzburg site



Hazardous substances are handled at the site with the GHS symbols shown. The protective measures are listed in the associated safety data sheets and must be observed.



In a chemical plant, **personal hygiene** of employees is of paramount importance. Eating and drinking is only allowed in the designated rooms. Soiled work clothes must be changed in good time. Clothing that has come into contact with chemicals must be changed immediately.

Leakage damage and other environmental damage must be reported immediately to the company fire brigade (emergency 0931/9084-222, otherwise tel. 0931/9084-218). The spread of damage must be limited by appropriate measures (e.g. covering the drain).



Warnung vor explosionsfähiger Atmosphäre

Hazardous areas are marked by yellow signs at the entrances (warning of explosive atmosphere)

Additional regulations and codes of conduct must be observed.



Hazardous areas may only be entered with safety shoes with an antistatic sole (at least EN 345 S1). Visitors are also allowed to wear sturdy shoes with electrostatic drainage strips. The function of the deflection strip must be checked with a test device. In hazardous areas, it is generally prohibited to carry or use equipment that can become a source of ignition, e.g. mobile phones, non-explosion-proof motor vehicles, transport vehicles, tools, walkie-talkies, flashlights, small appliances such as calculators, lighters, matches, etc. A permit is required for work in hazardous areas.



Appropriate protective equipment must be worn in the designated work areas.



Maximum speed on the factory premises is 20km/h. Park vehicles in designated parking areas and must not block access to safety devices!



Warnung vor Flurförderzeugen

traffic of industrial trucks on the road entire factory premises

Vertical ladders:

At the entire site, the use of vertical ladders as an ascent is only permitted with an existing order and a risk assessment/permit.



Smoking is strictly prohibited on the entire factory premises, including vehicles.



Photography is prohibited at the entire site (only possible with special permission).



It is prohibited to operate and start machines, systems and switches.



Absolute prohibition of alcohol and drugs on the entire factory premises.



The transport, storage and consumption of food and beverages is prohibited in areas with open chemical handling.



Electrical devices such as laptops or mobile phones are prohibited in designated areas. The only exception: specially approved equipment in Ex design.



Gefährliche Arbeiten nur mit Erlaubnisschein



Arbeiten in Höhe immer mit Absturzsicherung



Pets are not allowed.



Betreten von gekennzeichneten Gefahrenbereichen verboten



Entfernen und Umgehen von Sicherheitseinrichtungen verboten



Hazards from electromagnetic fields cannot be ruled out. Persons with modifiable bodily aids must report in advance.

Internal